


T. 134 R. 31 M. 5TH Coordinates: X _____ Y _____
NE 7 Corner common to sections 5, 6, 7, 8



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1869
 Original monument Post

Species	Bearing	Trees	
<u>Aspen</u>	<u>Aspen</u>	<u>OAK</u>	<u>OAK</u>
Diameter <u>13"</u>	<u>8"</u>	<u>4"</u>	<u>13"</u>
Bearing <u>N68E</u>	<u>N44W</u>	<u>S50E</u>	<u>S13 1/2 W</u>
Distance <u>18 LKS.</u>	<u>24 LKS.</u>	<u>31 LKS.</u>	<u>29 LKS.</u>

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 10/16/86 By Water Cure
 Location filed Cert. Filed Doc. #309791
 Monument Set a County east iron monument down 6" in road.
 Survey marker sign South 25'

Evidence of Subsequent Corner Restoration
 Year of search 1992 By Thomas P. Thiessen
Found 1.3' x 0.8' Flat top, egg shaped rock down 1.0'± at E. Set 1/2" iron pipe capped RLS 11/09/97.
Cert. Filed by Thomas P. Thiessen Doc. # 341567

Bearing Trees, Reference Objects
 Species Power Pole Tele. Ped. Corner Fence
 Diameter _____ Post _____
 Bearing S69 W N 3 E S 70 E
 Distance 91.15' 24.45' 38.52'

Bearing Trees, Reference Objects
Spike in RR tie Spike in RR tie Spike in top
Gate Post Gate Post tele. ped
NE SE NW
32.85' 19.49' 31.37'

E-5
 Subsequent Corner Restoration
 Year surveyed 5/2001 By CCSO
 Location filed file #2000.045
 Monument Found RR spike, down 0.5', 2'± S. of & Twp. Rd. Found egg shape rock down 1.0', placed next to gate post. Set 1986 CIM, down 0.75'. 1992 witnesses good. Survey marker sign is 31.0', SW. Add the following:
P. Pole S69°W, 109.09' to dbl hd nail
July 1902, Twp rd order shows no survey

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____