


T. 134 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

NE 16 Corner common to sections 9, 10, 15, 16



EXISTING SURVEYS

Original Government Survey

Year surveyed 1869  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing Trees			
	ASPEN	ASPEN	ASPEN	ASPEN
Diameter	6"	10"	8"	6"
Bearing	N 60 W	S 49 W	N 7 E	S 37 E
Distance	45 LKS	28 LKS	31 LKS	29 LKS

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed 1912 By John Curo  
Location filed COUNTY SURVEY RECORD BOOK "A" P 473-477  
Monument CORNER PREVIOUSLY ESTABLISHED BY CURO FROM S.E. B.T STUMP & ROOTS OF NE & SW BITS. RE-ESTAB LISHED CORNER FROM S.E. B.T STUMP. 1915, N. O. GORMAN, BOOK "B" P 484-495. FINE CORNER POSSIBLE I.M.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance

Evidence of Subsequent Corner Restoration

Year of search 1985 10/30 By Freeman  
Found 2" x 18" I.P. down 0.5' - pipe bent - straightened and reset SURVEY MARKER SIGN N 45 E 40' 10/23/86 set 2" x 18" telespar with an aluminum cap down 1".

Bearing Trees, Reference Objects

RED OAK	BURR OAK	N. PINE	TELE. BOX
10"	20"	10"	
N 63 W	N 51 E	S 27 E	S 66 W
133.45	94.75	156.80	56.15

J-13

Subsequent Corner Restoration

Year surveyed 10/2000 By CCSO  
Location filed #2000.023  
Monument Alum. Cap telespar, down 1.0', on E CP 35, 2' E N. of E 104th St. 1986 Witnesses good, Burr Oak NE is now a stump.

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
1-31-90 Cert. Filed by Walter Curo, RLS 11395 Doc. #318239