


Index No. N 17

CASS COUNTY LAND CORNER RECORD

T. 134 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

NE 22 Corner common to sections 14, 15, 22, 23



EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1867  
 Original monument POST

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Species	Bearing Trees			
	BL. PINE	BL. PINE	BL. PINE	BL. PINE
Diameter	<u>7"</u>	<u>8"</u>	<u>10"</u>	<u>10"</u>
Bearing	<u>S 79 E</u>	<u>S 84 W</u>	<u>S 86 E</u>	<u>N 25</u>
Distance	<u>30 LKS</u>	<u>33 LKS</u>	<u>18 LKS</u>	<u>20 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration  
 Year surveyed 1908 By John Curo  
 Location filed COUNTY SURVEY RECORD BOOK "A" P. 54-55  
 Monument 8x8x36" STONE

Evidence of Subsequent Corner Restoration  
 Year of search 1985 11/1 By Fredman  
Testimony of Paul Cracker - stone bladed  
out years ago.

Bearing Trees, Reference Objects

Species	J. PINE	J. PINE	N. PINE
Diameter	<u>6"</u>	<u>4"</u>	<u>8"</u>
Bearing	<u>N 36-08 E</u>	<u>S 61-14 W</u>	<u>S 38-17 E</u>
Distance	<u>35'</u>	<u>6.15'</u>	<u>7.80'</u>

Bearing Trees, Reference Objects

Species	J. PINE	N. PINE	N. PINE
Diameter	<u>6"</u>	<u>7"</u>	<u>15"</u>
Bearing	<u>N 40 W</u>	<u>N 49 E</u>	<u>S 55 E</u>
Distance	<u>45.03</u>	<u>86.83</u>	<u>77.60</u>

Set cast iron monument down 8"

N-17  
 Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Year of search \_\_\_\_\_ By \_\_\_\_\_  
2-5-90 Cert. Filed by Walter Curo, RLS 11395  
Doc. # 318318  
Sept. 1905; Twp rd order shows no survey

Remuneration certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_