


Index No. N 21

CASS COUNTY LAND CORNER RECORD



T. 134 R. 31 M. 5TH Coordinates: X _____ Y _____
NE 23 Corner common to sections 13, 14, 23, 24

EXISTING SURVEYS

Original Government Survey

Year surveyed 1869
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing	Trees	
Species	<u>BL. PINE</u>	<u>BL. PINE</u>	<u>BL. PINE</u>
Diameter	<u>14"</u>	<u>12"</u>	<u>8"</u>
Bearing	<u>S 63 W</u>	<u>N 35 E</u>	<u>S 80 E</u>
Distance	<u>8 LKS.</u>	<u>7 LKS.</u>	<u>2 B LKS.</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1908 By JOHN CURD
Location filed COUNTY SURVEY RECORD BOOK "A" 152-53
Monument FIND SW, NE, & SE B.T.S SET 8X8X36" STONE

Evidence of Subsequent Corner Restoration

Year of search 5/16/85 By FREEMAN, Glen Williams
BUCKHOE
Found 8" Sq stone w/ base in concrete, top broke off down 1.7' SET PIECE OF cast IRON OVER IT

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>P.P.</u>	<u>CFP</u>	<u>CFP</u>	
<u>N 43 E</u>	<u>N 50 W</u>	<u>S 57 E</u>	
<u>48.12'</u>	<u>46.03'</u>	<u>42.14'</u>	

N-21

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1-31-90 Cert. Filed by Walter Curd, BLS 11395
Doc. # 318242

June 1902, Twp rd order shows no survey

Remuneration certificate prepared _____

By _____

Filed at _____

Date _____