


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. R 13

CASS COUNTY LAND CORNER RECORD

T. 134 R. 31 M. 5th Coordinates: X _____ Y _____
NE 28 Corner common to sections 21, 22, 27, 28



○ = Corner

EXISTING SURVEYS

Original Government Survey
 Year surveyed 1867
 Original monument Post

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Species	Bearing Trees			
	Aspen	Aspen	Aspen	OAK
Diameter	<u>4"</u>	<u>9"</u>	<u>3"</u>	<u>12"</u>
Bearing	<u>N47E</u>	<u>N57W</u>	<u>S23W</u>	<u>S37E</u>
Distance	<u>15LKS</u>	<u>20LKS</u>	<u>12LKS</u>	<u>48LKS</u>

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1910 By John Curra
 Location filed County Book A pg. 44-45
 Monument Set 8x8x36 stone by proportion measurements.

Evidence of Subsequent Corner Restoration
 Year of search Feb. 1916 By _____
Imp rd survey shows no survey

Bearing Trees, Reference Objects
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____