

Index No. \_\_\_\_\_

CASS COUNTY LAND CORNER RECORD

T. \_\_\_\_\_ R. \_\_\_\_\_ M. \_\_\_\_\_ Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

Corner common to sections \_\_\_\_\_



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Index No. R17

CASS COUNTY LAND CORNER RECORD

T. 134 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 27 Corner common to sections 22, 23, 26, 27



EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1869  
 Original monument POST

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Species	Bearing	Trees	Rowwood
<u>OAK</u>	<u>OAK</u>	<u>ASPEN</u>	<u>Rowwood</u>
<u>16"</u>	<u>8"</u>	<u>10"</u>	<u>6"</u>
<u>SIDE</u>	<u>N40W</u>	<u>S70W</u>	<u>N81E</u>
<u>13 LKS</u>	<u>12 LKS</u>	<u>48 LKS</u>	<u>15 LKS.</u>

Original Bearing Trees Found  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed 1907 By JOHN CURO  
 Location filed COUNTY SURVEY RECORD BOOK "A" P46-47  
 Monument 8 X 8 X 3" STONE

Evidence of Subsequent Corner Restoration  
 Year of search 1985 11/4 By Freeman  
Co. Hwy Dept. plan on Co. Rd #34 show cut at corner eyed.

Bearing Trees, Reference Objects  
 Species OAK STUMP R. OAK  
 Diameter 8" 4"  
 Bearing N51-50E N41-51W  
 Distance 32.93' 18.15'

Bearing Trees, Reference Objects  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
 Year of search Feb. 1916 By \_\_\_\_\_  
Trap rd order shows no survey  
Sept. 1905; Trap rd order shows no survey

Remonumentation certificate prepared \_\_\_\_\_  
 Filed at \_\_\_\_\_

By \_\_\_\_\_  
 Date \_\_\_\_\_