

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. R21

CASS COUNTY LAND CORNER RECORD

T. 134 R. 31 M. 5TH Coordinates: X _____ Y _____
NE 26 Corner common to sections 23, 24, 25, 26



EXISTING SURVEYS

Original Government Survey

Year surveyed 1869
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees		
Species	<u>ASPEN</u>	<u>BL. PINE</u>
Diameter	<u>2"</u>	<u>6"</u>
Bearing	<u>N3W</u>	<u>NRE</u>
Distance	<u>48 LKS.</u>	<u>14 CHAINS?</u>

Original Bearing Trees Found		
Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1907 By JOHN CURD
Location filed COUNTY SURVEY RECORD BOOK "A" P48-49
Monument 8X8X36" STONE

Evidence of Subsequent Corner Restoration

Year of search 1985 11/4 By FREEMAN
testimony of Co. Engineer Worcester - he saw stone bladed out during road construction

Bearing Trees, Reference Objects

Species	<u>J. PINE</u>	<u>J. PINE</u>	<u>POPLAR STUMP</u>
Diameter	<u>8"</u>	<u>8"</u>	<u>10"</u>
Bearing	<u>N37-44W</u>	<u>N43-57E</u>	<u>S43W</u>
Distance	<u>49.85'</u>	<u>60.50'</u>	<u>42.20'</u>

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search June 1902 By _____
Twp rd order shows no survey
July 1905; Twp rd order shows no survey

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____