

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____


Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

T. 134 R. 31 M. 5TH Coordinates: X _____ Y _____
NE 30 Corner common to sections 19, 20, 29, 30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1869
Original monument POST

Species	Bearing	Trees	
<u>ASPEN</u>	<u>ASPN</u>	<u>ASPEN</u>	<u>ELM</u>
<u>24"</u>	<u>8"</u>	<u>2"</u>	<u>14"</u>
<u>SSE E</u>	<u>S32 W</u>	<u>N 52 E</u>	<u>N31 W</u>
<u>18 LKS</u>	<u>160 LKS</u>	<u>48 LKS</u>	<u>32 LKS</u>

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1915 By N. D. GORMAN
Location filed COUNTY BOOK 'B' P. 484-495
Monument FIND OLD GOVT BIT STUMP: 14" ELM
N31W 32 LKS POSSIBLE I.M.

Evidence of Subsequent Corner Restoration

Year of search 1985 11/4 By Freeman
Searched area w/ locator - no iron
Co. Hwy Dept plans Co. Rd # 34 - Show deep cut in area of corner.
SURVEY MARKER SIGN POST N45E 50'

Bearing Trees, Reference Objects

RED OAK	JACK PINE	COR. FENCE POST	PUR. POLE
<u>9"</u>	<u>5"</u>		
<u>S 25 W</u>	<u>S 55 E</u>	<u>S 10 E</u>	<u>N 31 E</u>
<u>126.15</u>	<u>154.70</u>	<u>108.40</u>	<u>89.75</u>

10/16/86 set cast iron mon.

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1-22-90 Cert. Filed by Walter Curo, RLS 11395
Doc. # 317969.
July 1902, Twp rd order shows no survey