

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____


Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

T. 134 R. 31 M. 5th Coordinates: X _____ Y _____
E 1/4 27 Corner common to sections 26, 27



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1869
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>TAM</u>	<u>SPRUCE</u>	_____
Diameter	<u>6"</u>	<u>6"</u>	_____
Bearing	<u>N75E</u>	<u>S82W</u>	_____
Distance	<u>18 LKS.</u>	<u>14 LKS.</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 5/16/86 By Freeman, Glen W. Williams
Location filed Backhoe
Monument dug in center of road's fence east
dug 8'E-W 12' N-S 2' deep
6" top 3' fill, 1.5' natural sand & gravel
SET CI Mon down 10"

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>J. PINE</u>	<u>J. PINE</u>	<u>BURR OAK</u>
Diameter	<u>8"</u>	<u>7"</u>	<u>12"</u>
Bearing	<u>N74W</u>	<u>S48W</u>	<u>S58E</u>
Distance	<u>30.05</u>	<u>33.35</u>	<u>63.23</u>

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
Location filed _____
Monument _____

Year of search _____ By _____

3-19-90 Cert Filed by Walter Curo, RLS 11395
Doc. # 319103