


T. 134 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 30 Corner common to sections 29, 30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1869  
Original monument 1867

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees	
Species <u>BL. PINE</u>	<u>BL. PINE</u>
Diameter <u>8"</u>	<u>8"</u>
Bearing <u>N37E</u>	<u>N60W</u>
Distance <u>18 LKS.</u>	<u>35 LKS</u>

Original Bearing Trees Found	
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Subsequent Corner Restoration

Year surveyed 1986 By T. FREEMAN  
Location filed \_\_\_\_\_  
Monument SET 2" X 36" TELESPAP MON WITH ALUM. CAP

Evidence of Subsequent Corner Restoration

Year of search July 1902 By \_\_\_\_\_  
Trusted order shows no survey

Bearing Trees, Reference Objects

Species <u>WHITE OAK</u>	<u>WHITE OAK</u>	<u>WHITE OAK</u>
Diameter <u>8</u>	<u>3</u>	<u>6"</u>
Bearing <u>NSE</u>	<u>S40E</u>	<u>S27W</u>
Distance <u>26.61</u>	<u>22.05</u>	<u>47.37</u>

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
3-19-90 Cert. Filed by Walter Curo, RLS 11395  
Doc. #319101.