

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____

Original Evidence Found

Year of search _____ by _____

Monument found _____

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed: _____

Monument: _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Location filed: _____

Monument: _____

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed: _____

Monument: _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____


Location filed: _____

Monument: _____

Index No. V 11

CASS COUNTY LAND CORNER RECORD

T. 134 R. 31 M. 5TH Coordinates: X _____ Y _____
N¹⁴ 33 Corner common to sections 28, 33



○ = Corner

EXISTING SURVEYS

Original Government Survey
 Year surveyed 1869
 Original monument Post

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Bearing Trees
 Species ASPEN ASPEN
 Diameter 5" 14"
 Bearing N8RE S18 1/2 E
 Distance 130 LKS. 140 LKS.

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1915 By N. D. GORMAN
 Location filed COUNTY BOOK "B" P. 484-495
 Monument SET CORNER PROPORTIONALLY. POSSIBLE TIM.

Evidence of Subsequent Corner Restoration Found
 Year of search 1985 10/30 By Freeman
Found 2" capped 11.
Survey marker sign North 1"

Bearing Trees, Reference Objects
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects

<u>RED OAK</u>	<u>BURR OAK</u>	<u>CFP</u>
<u>6"</u>	<u>12"</u>	
<u>N 60 E</u>	<u>S 25 E</u>	<u>S 10 W</u>
<u>40.82</u>	<u>83.08</u>	<u>15.52</u>

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
CERT. W. C. CO 1990 Doc # 3198A
1999 - Landecker + Assoc.
Cert. of Survey indicates monument found.
June 1902, Typ rd order shows no survey

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____