


T. 134 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 36 Corner common to sections 25, 36



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 189  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing	Trees
<u>OAK</u>	<u>OAK</u>	
<u>10"</u>	<u>4"</u>	
<u>S10E</u>	<u>N8E</u>	
<u>ROCKS</u>	<u>ROCKS</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed 5/16/86 By Freeman, Glen Williams  
Location filed Backhoe  
Monument dug in center of E-W rd, fence north  
and 9' rail south  
dug 9' N-S 12' E-W 2.5' deep  
6" top 2' natural sand found nothing

Evidence of Subsequent Corner Restoration

Year of search July 1905 By \_\_\_\_\_  
Twp rd order shows no survey

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>J. PINE</u>	<u>N. PINE</u>	<u>W. PINE</u>
<u>7"</u>	<u>10"</u>	<u>7"</u>
<u>N54W</u>	<u>S46W</u>	<u>S28E</u>
<u>53.80</u>	<u>48.35</u>	<u>84.25</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERT. W. C. R. 1990 Doc. # 319106