


T. 134 R. 31 M. 5TH Coordinates: X _____ Y _____
NE 36 Corner common to sections 25, 36 AND 30, 31-134-30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1858
Original monument lost

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trces	
<u>PINE</u>	<u>PINE</u>	<u>PINE</u>	<u>PINE</u>
Diameter <u>18"</u>	<u>16"</u>	<u>20"</u>	<u>10"</u>
Bearing <u>N10W</u>	<u>NRE</u>	<u>S65W</u>	<u>S30E</u>
Distance <u>69 LKS</u>	<u>64 LKS</u>	<u>44 LKS</u>	<u>16 LKS</u>

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1907 By JOHN CURO
Location filed SURVEY RECORD BOOK 'A' P. 32, 33
Monument END SE 1/4 SW BITS SET 8X8X36" STONE
JUNE 16 1921 J.M. GREENE INTERSECTS RANGE
LINE FROM EAST 269' NORTH OF CORNER
CURO BOOK 173 PAGE 20

Evidence of Subsequent Corner Restoration

Year of search 1985 11/8 By FREEMAN
Found 8" sq. stone at P.L. roads N E W
stone flush on S. side - up 0.3' on N. side
Stone is on W. side of trail running South
SET 1 1/2 x 2 1/2" IRON PIPE AS GUARD ST

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>N. PINE</u>	<u>J. PINE</u>	
Diameter <u>8"</u>	<u>10"</u>	
Bearing <u>N44-31E</u>	<u>N74-50E</u>	
Distance <u>41.60'</u>	<u>34.75'</u>	

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>JACK PINE</u>	<u>C.P.R.</u>	<u>C.P.R.</u>
Diameter <u>5"</u>		
Bearing <u>N 25. E</u>	<u>S 2 W</u>	<u>N 40 W</u>
Distance <u>35.45</u>	<u>24.90</u>	<u>50.20</u>

V-25

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
4-23-90 Cert. Filed by Walter Curo, RLS 11395
Dr. # 319822

Feb 2003 P. Landecker #17008
Cert. of Surv. shows mon. found

July 1905, Twp rd order shows no survey.

Remuneration certificate prepared _____ By _____
Filed at _____ Date _____