134 R 3/ M. 57H Coordinates: X E'/4 35 Corner common to sections 35,36	
EXI	ISTING SURVEYS
Original Government Survey	Original Evidence Found
ear surveyed 1869	Year of searchBy
riginal monument Post	Monument found O = Corner
Species N. PINE Rearing Trees Diameter 17" 12"	Original Bearing Trees Found
Species N. FINE Keen	Species Diameter
Diameter 17" 12"	Bearing —
Bearing Notice Native	Daditing
Distance 80 Lks. 38LKS.	
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration
(ear surveyed By	Year of searchBy
Location filed	
Monument	
Defense Objects	Bearing Trees, Reference Objects
Bearing Trees, Reference Objects	
Species	
Diameter	
Bearing	
Bearing	Evidence of Subsequent Corner Restoration Found
Subsequent Corner Restoration (ear surveyed By	
Subsequent Corner Restoration ear surveyed By	Evidence of Subsequent Corner Restoration Found
Subsequent Corner Restoration ear surveyed By ocation filed	Evidence of Subsequent Corner Restoration Found
Subsequent Corner Restoration ear surveyed By ocation filed	Evidence of Subsequent Corner Restoration Found
Subsequent Corner Restoration ear surveyed By ocation filed	Evidence of Subsequent Corner Restoration Found
Subsequent Corner Restoration ear surveyed By ocation filed	Evidence of Subsequent Corner Restoration Found
Subsequent Corner Restoration ear surveyed By	Evidence of Subsequent Corner Restoration Found
Subsequent Corner Restoration ear surveyed By ocation filed	Evidence of Subsequent Corner Restoration Found
Subsequent Corner Restoration ear surveyed By ocation_filed	Evidence of Subsequent Corner Restoration Found
Subsequent Corner Restoration ear surveyed By ocation filed	Evidence of Subsequent Corner Restoration Found
Subsequent Corner Restoration ear surveyed By ocation filed	Evidence of Subsequent Corner Restoration Found
Bearing	Evidence of Subsequent Corner Restoration Found
Subsequent Corner Restoration ear surveyed By ocation filed	Evidence of Subsequent Corner Restoration Found