


Index No. X 5

CASS COUNTY LAND CORNER RECORD

T. 134 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 31 Corner common to sections 31, 32



EXISTING SURVEYS

Original Government Survey

Year surveyed 1869  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species ASPEN ASPEN  
Diameter 4" 5"  
Bearing N60E WEST  
Distance 15 LKS. 17 LKS.

Original Bearing Trees Found  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

O = Corner

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search 1985 11/7 By Freeman  
Backhoe operator Glen Williams dug 12'x12'  
hole 2.5' deep.  
6" sand top, 1' fill, 1' natural ground  
is sandy clay  
SET 2" x 18" TELESPAR MON.

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

RED OAK RED OAK CFP  
12" 12"  
N 87 W S 38 W S 87 E  
66.63 67.27 35.70

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
3-19-90 Cert. Filed by Walter Curo, RLS 11395  
Doc. # 319107.  
July 1902, Twp rd order shows no survey

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_