


Index No. A 5

CASS COUNTY LAND CORNER RECORD

T. 134 R. 32 M. 5TH Coordinates: X _____ Y _____
NE 6 Corner common to sections 5, 6 AND 31, 32-135-32



EXISTING SURVEYS

Original Government Survey

Year surveyed 1858

Original monument Post

Species	Bearing	Trees	SP. PINE	SP. PINE
Diameter	<u>8"</u>	<u>8"</u>	<u>10"</u>	<u>9"</u>
Bearing	<u>S47E</u>	<u>S26W</u>	<u>N29W</u>	<u>N44E</u>
Distance	<u>10 LKS.</u>	<u>12 LKS</u>	<u>28 LKS.</u>	<u>45 LKS</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

O = Corner

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search 8/25/86 By Surveyors office

Found 1 1/2" x 16" Car spring 12.1' N. of C.W

in line w/ C.N. - replaced with cast iron

monument down 6" - car spring set on N. side

of cast iron.

Certificate - Curro - 1987 - Doc # 297513

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Bearing Trees, Reference Objects

Jack Pine	Jack Pine	Jack Pine	P.P.
Diameter	<u>8"</u>	<u>6"</u>	<u>8"</u>
Bearing	<u>N32°E</u>	<u>N69°E</u>	<u>S5°E</u>
Distance	<u>22.05'</u>	<u>9.98'</u>	<u>70.74'</u>
			<u>61.79'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Certificate - Walt Curro - 1987

Doc. # 297513

April 1992 T. Theissen # 16097

Cert. of Survey shows monument found

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____