Index No. E17

CASS COUNTY LAND CORNER RECORD

T. 134 R. 32 M. 5TH Coordinates: X _____ Y _____

NE 10 Corner common to sections 2, 3, 10, 11



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870

Original monument Post

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	TAM.	TAM.	TAM.	TAM.
Diameter	5"	7"	6"	6"
Bearing	N38W	N27E	S19W	S34E
Distance	5LKS	8 LKS.	7LKS.	20LKS.

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 7/2003 By CCSO

Location filed #2001.022

Monument Found 60d nail down 0.1', on 2 2 Co. Rd #106 & 100th St.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	W. Oak	Tel Ped Post	P. Pole	P. Pole
Diameter	11"			
Bearing	S68°W	N58°W	N40°E	S50°E
Distance	174.57'*	33.33'*	241.35'*	59.46'*

*distance to double head nail

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____