


Index No. E 25

CASS COUNTY LAND CORNER RECORD

T. 134 R. 32 M. 5TH Coordinates: X _____ Y _____
NE 12 Corner common to sections 1, 12 AND 6, 7-134-31



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1858

Original monument POST

Species	Bearing	Trees	
<u>SPRUCE</u>	<u>SPRUCE</u>	<u>ASPEN</u>	<u>W. BIRCH</u>
<u>7"</u>	<u>6"</u>	<u>11"</u>	<u>10"</u>
<u>N37°4E</u>	<u>S74°4E</u>	<u>S17W</u>	<u>N62°14W</u>
<u>21 LKS.</u>	<u>12 LKS.</u>	<u>8 LKS.</u>	<u>82 LKS.</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1916 By _____

Location filed _____

Monument Co DITCH SURVEY BK 25 BOX 2
OF Co DITCH SURVEY BOOKS, PG 11

Evidence of Subsequent Corner Restoration

Year of search 2000 JULY By CCSO

Find. in place; 4" CIM. Located 18.5' W of
Co TH 64 and 3' N E 100th St. sul, E Dead
End Rd.

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Bearing Trees, Reference Objects

<u>P. Pole</u>	<u>B. Oak</u>	<u>P.K. in CMP</u>	<u>P.K. in CMP</u>
	<u>8"</u>		
<u>N 70° W</u>	<u>S 46° W</u>	<u>N 72° E</u>	<u>S 73° E</u>
<u>81.28</u>	<u>137.87'</u>	<u>59.06</u>	<u>58.40'</u>

(Find. 16d sec-1)

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument - Corner GPS 10/15/02 CCSO
Clon, down 0.2, 19' ± W. of #64,
2' ± N. of 100th St.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____