


Index No. T 21

CASS COUNTY LAND CORNER RECORD

T. 134 R. 32 M. 5TH Coordinates: X _____ Y _____
E/4 26 Corner common to sections 25, 26



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870

Original monument Post

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species <u>LINDEN</u>	<u>OAK</u>	_____	_____
Diameter <u>0"</u>	<u>14"</u>	_____	_____
Bearing <u>S49 E</u>	<u>S22 W</u>	_____	_____
Distance <u>13 LKS.</u>	<u>19 LKS.</u>	_____	_____

Original Bearing Trees Found

Species _____	_____	_____	_____
Diameter _____	_____	_____	_____
Bearing _____	_____	_____	_____
Distance _____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 11/2/1998 By LS 13334

Location filed CASS CO. SURVEYOR

Monument FOUND COUNTY MONUMENT

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____	_____	_____	_____
Diameter _____	_____	_____	_____
Bearing _____	_____	_____	_____
Distance _____	_____	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____