


Index No. E 13

CASS COUNTY LAND CORNER RECORD

T. 135 R. 29 M. 5TH Coordinates: X _____ Y _____

NE 9 Corner common to sections 3, 4, 9, 10



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing	Trees	
Species	<u>N. Pine</u>	<u>N. Pine</u>	<u>N. Pine</u>
Diameter	<u>15"</u>	<u>4"</u>	<u>10"</u>
Bearing	<u>N 58 1/2 E</u>	<u>N 45 1/2 W</u>	<u>S 71 1/2 E</u>
Distance	<u>21 LKS.</u>	<u>55 LKS.</u>	<u>72 LKS.</u>

Original Bearing Trees Found

Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Subsequent Corner Restoration

Year surveyed 1917 By Curo
Location filed microfilm - roll 1105 BK 56 R 121
Monument End stumps of NE, SE & SW B&T's
set corner

Evidence of Subsequent Corner Restoration

Year of search 11/3/77 By M. LANDECKER
FOUND 2" IRON PIPE 100' NORTH OF BITUM. ROAD
ON WEST SIDE OF GRAVEL ROAD
LANDECKER RECORDS INDEX #1

	Bearing	Trees	Reference Objects
Species	<u>N. Pine</u>	<u>J. Pine</u>	<u>J. Pine</u>
Diameter	<u>18"</u>	<u>4"</u>	<u>7"</u>
Bearing	<u>N 41-12 W</u>	<u>N 62-11 E</u>	<u>S 64-50 W</u>
Distance	<u>76.71'</u>	<u>84.32'</u>	<u>107.31'</u>

	Bearing	Trees	Reference Objects
Species	<u>OAK</u>	<u>OAK</u>	<u>OAK</u>
Diameter	<u>7"</u>	<u>6"</u>	<u>9"</u>
Bearing	<u>WNW</u>	<u>ENE</u>	<u>SSW</u>
Distance	<u>22.66</u>	<u>39.78</u>	<u>16.20</u>

ALL OBL BLAZED

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - SILVER BAY HAVEN
DEAN ANDERSON 1968

Remuneration certificate prepared _____ By _____
Filed at _____ Date _____