


T. 135 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 14 17 Corner common to sections 8, 17



○ = Corner

EXISTING SURVEYS

Original Government Survey  
Year surveyed 1865  
Original monument POST

Original Evidence Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species DEAD N. PINE DEAD N. PINE  
Diameter 20" 20"  
Bearing N 76 E S 39 1/4 E  
Distance 88 LKS 33 LKS.

Original Bearing Trees Found  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration  
Year surveyed 1976 By D. ANDERSON  
Location filed \_\_\_\_\_  
Monument 1 1/2" Iron pipe

Evidence of Subsequent Corner Restoration  
Year of search 1982 By \_\_\_\_\_  
Survey Technician T. Freeman & Forester D. Marcum  
Found 1 1/2" i.p. VP 2 1/2' ALSO Found 1976 TIES  
POSSIBLE ROTTENSTUMP OF SE ORIG. BIT.

Bearing Trees, Reference Objects  
Species Aspen oak J. Pine  
Diameter 9" 4" 14"  
Bearing NW NE SE  
Distance 2.7' 16.25' 27.8'

Bearing Trees, Reference Objects  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument November 1986 D. Landecker #17008  
Cert. of Survey shows monument found

Evidence of Subsequent Corner Restoration Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_