


Index No. \_\_\_\_\_

CASS COUNTY LAND CORNER RECORD

T. \_\_\_\_\_ R. \_\_\_\_\_ M. \_\_\_\_\_ Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

Corner common to sections \_\_\_\_\_



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Index No. \_\_\_\_\_

CASS COUNTY LAND CORNER RECORD

T. \_\_\_\_\_ R. \_\_\_\_\_ M. \_\_\_\_\_ Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

Page \_\_\_\_\_ of \_\_\_\_\_

Corner common to sections \_\_\_\_\_

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found


Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Index No. A 13

CASS COUNTY LAND CORNER RECORD

T. 135 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 4 Corner common to sections 3, 4 AND 33, 34-136-30



EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1858  
 Original monument POST

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Species	Bearing	Trees
<u>Aspen</u>	<u>PINE</u>	<u>PINE</u>
Diameter <u>16"</u>	<u>24"</u>	<u>18"</u>
Bearing <u>N48E</u>	<u>N12W</u>	<u>S74W</u>
Distance <u>120 LKS.</u>	<u>106 LKS.</u>	<u>94 LKS.</u>

Original Bearing Trees Found  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

O = Corner

Subsequent Corner Restoration  
 Year surveyed 1914 By JOHN Curo  
 Location filed COUNTY SURVEY RECORD BOOK "B" P. 46-48  
 Monument Two old Govt. B.T. STUMPS: 24" PINE N12W  
106 LKS, 18" PINE S74W 94 LKS. SET HUB.  
SURVEY OF STATE RURAL HWY 80 SHOWS STAKE AND  
TIES BELOW

Evidence of Subsequent Corner Restoration  
 Year of search Oct. 1903 By W.H. Hallett  
Two rd order shows survey  
1914 - also on microfilm - roll MS BK 94 P. 57

Bearing Trees, Reference Objects  
 Species POPLAR POPLAR  
 Diameter TACK TACK  
 Bearing NW SE  
 Distance 54.5' 58.3'

Bearing Trees, Reference Objects  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

A13  
 Subsequent Corner Restoration  
 Year surveyed 8/00 By CCSO  
 Location filed CCSO  
 Monument Found 1" ODIP, flush, 2' E. of  
& C.R. #1 & 2' N. of & 72nd st. Fd  
existing witnesses and added.  
 CFP N53°E, 48.44' 60d spike  
 CFP S51°E, 56.30' 60d spike  
 P. Pole N61°W, 73.48' 60d spike  
 Stop Sign S65°W, 50.83' N. flange  
5" N. Pine N16°E, 124.25'  
\* distance to double head nail  
- Corner GPS CCSO 9/12/02  
1" ODIP, 1' ± E. of & CR #1,  
3' ± N. of & 72nd st  
 March 2004 B. Grivna #17253  
 Cert. of Survey shows monument found  
 April 1911 - Two Road order shows no survey.

Evidence of Subsequent Corner Restoration Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
PLAT - PLEASANT HILL CEMETARY  
W.H. LUFFEMAN 1914