


Index No. E22

CASS COUNTY LAND CORNER RECORD

T. 135 R. 30 M. 5th Coordinates: X _____ Y _____
W 1/16 Corner common to sections 1, 12



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed Sept 1916 By _____
Location filed Twp rd order shows no survey
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 2000 By CCSO
Find. in place: 2" I.M. Located @
C.R. 29. Fencelines run both N & S
from cor. position as noted.
AUG. 2000 - SET A MAG NAIL from ties
POST CONSTR.

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Ash Maple
4" 13"
S 48°E S 11°E
55.11' 49.07'

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remuneration certificate prepared _____ By _____

Filed at _____ Date _____