


T. 135 R. 30 M. 5TH Coordinates: X NE 17 Y 8, 9, 16, 17
Corner common to sections 8, 9, 16, 17



○ = Corner

EXISTING SURVEYS

Original Government Survey
Year surveyed 1869
Original monument Post

Bearing Trees

Species	<u>MAPLE</u>	<u>OAK</u>	<u>OAK</u>	<u>OAK</u>
Diameter	<u>10"</u>	<u>7"</u>	<u>5"</u>	<u>6"</u>
Bearing	<u>S40E</u>	<u>N50E</u>	<u>N60W</u>	<u>S20W</u>
Distance	<u>23 LKS</u>	<u>18 LKS</u>	<u>27 LKS</u>	<u>10 LKS.</u>

Original Evidence Found
Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1914 By JOHN CURD
Location filed COUNTY SURVEY RECORD BOOK B' P. 57-61
Monument IND STONE SET BY B.B. BARTLETT
A SURVEY OF STATE RURAL HWY 60 SHOWS STAKE - Box
B' 4972-473
1914 - also on microfilm roll 115 BK 94 P. 123-125

Evidence of Subsequent Corner Restoration
Year of search 1914 By _____
Co DITCH SURVEY BK 22 BOX 3 OF Co.
DITCH SURVEY BOOKS, P 6 32

June 1913, Twp rd order shows no survey

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search Feb. 1904 By W. H. Hallett
Twp rd order shows survey

Oct. 1903 W. H. Hallett
Twp rd order shows survey

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____