


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. N 17

CASS COUNTY LAND CORNER RECORD

T. 135 R. 31 M. 5TH Coordinates: X _____ Y _____
NE 22 Corner common to sections 14, 15, 22, 23



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1869
 Original monument Post

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

	Bearing	Trees	
Species	<u>Aspen</u>	<u>OAK</u>	<u>Aspen</u>
Diameter	<u>20"</u>	<u>18"</u>	<u>8"</u>
Bearing	<u>S77E</u>	<u>S71W</u>	<u>N13E</u>
Distance	<u>33LKS.</u>	<u>26LKS.</u>	<u>50LKS.</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration
 Year of search Oct. 1905 By W. H. Hallett
Twp rd order shows survey
Oct. 1903; W. H. Hallett
Twp rd order shows survey

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____