Index No. V 19

CASS COUNTY LAND CORNER RECORD

T. 135 R. 30 M. 5TH Coordinates: X _____ Y _____

N 1/4 35 Corner common to sections 26, 35



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1869

Original monument Post

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	TAM	SPRUCE		
Diameter	6"	12"		
Bearing	N19W	S25E		
Distance	22 LKS.	17 LKS.		

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1921 By E.B. HORST

Location filed COUNTY RESURVEY "E-33"

Monument IRON MONUMENT

1921, COUNTY BOOK "C" P412 SET 2x48" I.M.

Evidence of Subsequent Corner Restoration

Year of search Aug. 2004 By B. Grivna #17253

Cert. of Sur. Shows mon. found

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

(V-19)

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

March 2005 B Grivna #17253
Cert of Survey shows monument found

8/2003 - CCSO #2001.024 found 2"x15" ODIP, on ℄ Co. Rd #107, leaning East, Locate bottom and plumb, lower to 0.3 below surface, witness:

12" W. Oak N70°W, 114.55'*
9" B of G.I. N35°E, 49.31'*
P. Pole S32°E, 41.57'*
*distance to double head nail

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____