


Index No. A 11

CASS COUNTY LAND CORNER RECORD

T. 135 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N<sup>1</sup>/<sub>4</sub> 4 Corner common to sections 4 AND 33-136-31



EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1858  
 Original monument POST

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Bearing Trees  
 Species BL. ASH W. OAK  
 Diameter 9" 9"  
 Bearing S85E NORTH  
 Distance 9 LKS 7 LKS

Original Bearing Trees Found  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed 1912 By JOHN CURO  
 Location filed COUNTY SURVEY RECORD BOOK "B" P 12-28  
 Monument SET 4x4x60" TAM POST PROPORTIONALLY.  
SET 2 1/2 x 48" GALV. I.P. IN CONCRETE

Evidence of Subsequent Corner Restoration  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects  
 Species PINE STUMP STUMP  
 Diameter TACK TACK  
 Bearing S76-28W N29-28E  
 Distance 205' 34.60'  
2.05' OR 205'

Bearing Trees, Reference Objects  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
Oct. 1912 Makenny  
Twp Rd Survey indicates corner established

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_