


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. A 13

CASS COUNTY LAND CORNER RECORD

T. 135 R. 31 M. 5TH Coordinates: X _____ Y _____
NE 4 Corner common to sections 3, 4 AND 33, 34-136-31



EXISTING SURVEYS

Original Government Survey

Year surveyed 1858
Original monument POST

Species	Bearing	Trees
<u>W. BIRCH</u>	<u>W. BIRCH</u>	<u>W. BIRCH</u>
<u>5"</u>	<u>6"</u>	<u>7"</u>
<u>N60W</u>	<u>SSE</u>	<u>S45W</u>
<u>44 LKS.</u>	<u>25 LKS.</u>	<u>22 LKS.</u>

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1912 By JOHN CURO
Location filed COUNTY SURVEY RECORD BOOK B" P. 12-28
Monument SET 8x12x18" GRANIT BOULDER W/ X" ON DP
SET 2 1/2 x 48" GALV. I.P. IN CONCRETE

Evidence of Subsequent Corner Restoration

Year of search 6/1905 By N.W. Hicks
Trap Road Order, Surveyor's Report
notes stake established from
3 stumps.

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>PINE STUMP</u>	<u>EUM.</u>	_____
<u>8"</u>	_____	_____
<u>S74-09W</u>	<u>S55-19E</u>	_____
<u>175.40'</u>	<u>221.60'</u>	_____

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

A-13 Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search 1999 By CCSO
Ind. impl. 2 1/4" ODIP in poor cond,
top has been bent. Located 3' S of &
72nd St. to the East and 1' W of
57th Ave.
REF. TIES: 8" W. Oak N 46° E 55.90'
11" W. Oak S 61° E 105.17'
5" Maple S 40° W 45.21'
3" W. Oak N 62° W 46.50'

* ties w/ dbl. hd. nails up 1.0'

-Corner GPS 10/10/02 CCSO
2" ODIP, down 0.5', on & &

Oct. 1912 Makemy
Trap Rd Order indicates corner established

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____