

Index No. \_\_\_\_\_

CASS COUNTY LAND CORNER RECORD

T. \_\_\_\_\_ R. \_\_\_\_\_ M. \_\_\_\_\_ Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

Corner common to sections \_\_\_\_\_



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Index No. A 17

CASS COUNTY LAND CORNER RECORD

T. 135 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 3 Corner common to sections 2, 3 AND 34, 35-136-31



EXISTING SURVEYS

Original Government Survey  
Year surveyed 1858  
Original monument POST

Original Evidence Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing Trees			
	<u>PINE</u>	<u>PINE</u>	<u>W. BIRCH</u>	<u>BL. OAK</u>
Diameter	<u>24"</u>	<u>30"</u>	<u>18"</u>	<u>7"</u>
Bearing	<u>S82E</u>	<u>S40W</u>	<u>N77W</u>	<u>N18E</u>
Distance	<u>43LKS.</u>	<u>33LKS.</u>	<u>52LKS.</u>	<u>20LKS.</u>

Original Bearing Trees Found				
Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration  
Year surveyed 1912 By JOHN CURD  
Location filed COUNTY SURVEY RECORD BOOK B" P. 12-28  
Monument FND OLD CANT BITS: 24" PINE S82E 43LKS.,  
30" PINE S40W 33LKS, 7" BL. OAK N18E 20LKS.  
SET 2x2x30" OAK HUB  
SET 2 1/2 x 48" GALV. I.P. IN CONCRETE

Evidence of Subsequent Corner Restoration  
Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects	
Species	<u>BL. OAK</u> <u>POPLAR</u>
Diameter	<u>7"</u> <u>6"</u>
Bearing	<u>N73-42W</u> <u>N50E</u>
Distance	<u>67.60'</u> <u>70.90'</u>

Bearing Trees, Reference Objects				
Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
OCT 1912 Makenny  
Trap Rd order indicates corner established

Re monumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_