


Index No. J 15

CASS COUNTY LAND CORNER RECORD

T. 136 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 15 Corner common to sections 10, 15



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870  
Original monument POST

Bearing Trees	
Species <u>TAM</u>	<u>TAM</u>
Diameter <u>8"</u>	<u>10"</u>
Bearing <u>NR 1/2 W</u>	<u>S 32 1/2 E</u>
Distance <u>14 LKS.</u>	<u>11 LKS.</u>

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species _____	_____	_____	_____
Diameter _____	_____	_____	_____
Bearing _____	_____	_____	_____
Distance _____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search 1995 2-6 By John D. Walker  
Placed a 3/4" x 24" iron rod w/ aluminum cap stamped: "DNR Survey Marker" (up 0.1) at West end of high ground w/ Elm trees.  
4-4-95 Cert. Filed by John D. Walker, RLS 16098.  
Doc # 365900

Bearing Trees, Reference Objects

Species _____	_____	_____	_____
Diameter _____	_____	_____	_____
Bearing _____	_____	_____	_____
Distance _____	_____	_____	_____

Bearing Trees, Reference Objects

Twin Elm	Elm	Elm
<u>7</u>	<u>5"</u>	<u>5"</u>
<u>N 6 E</u>	<u>N 68 E</u>	<u>S 72 E</u>
<u>41.44</u>	<u>15.75</u>	<u>33.88</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_