


Index No. J 17

CASS COUNTY LAND CORNER RECORD

T. 135 R. 31 M. 5TH Coordinates: X _____ Y _____
NE 15 Corner common to sections 10, 11, 14, 15



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1870
 Original monument POST

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Species	Bearing	Trees	Distance
<u>BR. OAK</u>	<u>ELM</u>	<u>BL. ASH.</u>	<u>TAM</u>
<u>18"</u>	<u>12"</u>	<u>6"</u>	<u>6"</u>
<u>N79 1/2 E</u>	<u>S74 1/2 E</u>	<u>N86 W</u>	<u>S20 W</u>
<u>18 LKS.</u>	<u>37 LKS.</u>	<u>17 LKS.</u>	<u>45 LKS.</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration
 Year of search 1914 7-13 By John D. Walker
 Placed a 3/4" x 3/4" iron rod w/ alumn cap stamped: "DNR
 survey marker" (up 0.2') and 6' SW of water's edge
 on high ground protruding into a swamp.
 4-4-95 Cert. Filed by John D. Walker, RLS 16698
 Doc # 365901

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>DNR signs + Posts</u>	<u>Elm</u>	<u>Elm</u>	<u>Birch</u>
<u>1' N + 1' W of mon.</u>	<u>9"</u>	<u>5"</u>	<u>3"</u>
_____	<u>N40 W</u>	<u>S64 W</u>	<u>S5 W</u>
_____	<u>27.30</u>	<u>7.11</u>	<u>14.37</u>

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____