


T. 135 R. 31 M. 5TH Coordinates: X _____ Y _____
NE 14 Corner common to sections 11, 12, 13, 14



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870

Original monument Post

Species	Bearing	Tree	Distance
<u>Y. BIRCH</u>	<u>BALSAM</u>	<u>W. PINE</u>	<u>Y. BIRCH</u>
<u>6"</u>	<u>7"</u>	<u>36"</u>	<u>10"</u>
<u>N 1/4 E</u>	<u>N 60 W</u>	<u>S 79 W</u>	<u>S 44 1/2 E</u>
<u>21 LKS.</u>	<u>14 LKS.</u>	<u>23 LKS.</u>	<u>46 LKS.</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1994 7-13 By John D. Walker

Placed a 3/4" x 3/4" iron rod w/ alum. cap stamped "DNR survey marker" (up 02) in low marshy area 73.5' S of center line Deer Trail Drive.

4-4-95 Cert. filed by John D. Walker, R/S 16098

Doc. #365902

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Ash</u>	<u>Elm</u>	<u>Elm</u>	
<u>10"</u>	<u>4"</u>	<u>3"</u>	
<u>N 54 E</u>	<u>N 58 W</u>	<u>S 15 E</u>	
<u>25.60</u>	<u>5.56</u>	<u>4.55</u>	

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

PLAT - WILDERNESS PARK ESTATES 4th ADDITIONAL

DONALD COULTER - 1972

1999 - CC50 -

Fnd. incl. 73' S of E.R.L., 3/4" Iron Rod w/ Alum. cap stamped "DNR SURVEY MKR"