


Index No. N 11

CASS COUNTY LAND CORNER RECORD

T. 135 R. 31 M. 5+4 Coordinates: X 468221.49 Y 225425.52
N 1/4 R 1 Corner common to sections 16, 21



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870

Original monument Post

Species	Bearing	Trees
<u>BR. OAK</u>	<u>E 6M</u>	
Diameter <u>8"</u>	<u>12"</u>	
Bearing <u>S 85 1/2 E</u>	<u>N 55 W</u>	
Distance <u>81 LKS</u>	<u>84 LKS</u>	

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Bearing	Trees
_____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Subsequent Corner Restoration

Year surveyed 1920 By LINCOLN MACKAY

Location filed COUNTY BOOK "C" P 372

Monument SET 2x4x8" I.M. PROPORTIONALLY

Evidence of Subsequent Corner Restoration

Year of search 6/98 By DNR

Set DNR Survey marker, up 0.2', midway on line between Sec. Corners, 2.5' W. and 0.5' S. of fence lines.

Bearing Trees, Reference Objects

Species	Bearing	Trees
<u>Poplar</u>		
Diameter <u>15"</u>		
Bearing <u>N 0-30 E</u>		
Distance <u>239.0'</u>		

Bearing Trees, Reference Objects

Species	Bearing	Trees
<u>Ash</u>		
Diameter <u>14"</u>		
Bearing <u>N 20° W</u>		
Distance <u>29.33'*</u>		
<u>Ash</u>		
Diameter <u>6"</u>		
Bearing <u>S 35° E</u>		
Distance <u>18.15'*</u>		
<u>Fence Cor</u>		
<u>Post</u>		
Bearing <u>N 72° E</u>		
Distance <u>2.73'*</u>		

*distance to DNR RP

N-11 Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Re monumentation certificate prepared 5/31/01

Filed at Cass Co. Recorder #441843

By J. Walker

Date _____