


Index No. N 9

CASS COUNTY LAND CORNER RECORD

T. 135 R. 31 M. 5TH Coordinates: X 465,559.07 Y 225,433.88
NE 20 Corner common to sections 16,17,20,21



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1870
 Original monument POST

Species	Bearing	Trees	
<u>OAK</u>	<u>OAK</u>	<u>OAK</u>	<u>OAK</u>
<u>14"</u>	<u>10"</u>	<u>8"</u>	<u>9"</u>
<u>N42 1/2 W</u>	<u>S76 E</u>	<u>S81 1/2 W</u>	<u>N50 E</u>
<u>33 LKS</u>	<u>30 LKS</u>	<u>16 LKS</u>	<u>28 LKS</u>

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration
 Year surveyed 1920 By LINCOLN
 Location filed COUNTY BOOK 'C' P 371
 Monument FND old Post & Set 24 1/2' 1P

Evidence of Subsequent Corner Restoration
 Year of search 4/98 By DNR
Found 1" IP, down 24", on E N-S Rd, 4 1/2 N. of E E-W Rd. Set DNR Survey cap in pipe, down 0.3'.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>OAK</u>	<u>10"</u>	<u>S54 E</u>	<u>55.2'</u>

Bearing Trees, Reference Objects

Fence Cor	Fence Cor	Tele Post
<u>Post</u>	<u>Post</u>	
<u>N58°W</u>	<u>N32°E</u>	<u>S35°W</u>
<u>77.39'*</u>	<u>37.26'*</u>	<u>51.50'*</u>

*distance to MNDNR RP

N-9

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

June 1921 P.A. Bean
Trap Rd order shows corner

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____

May 1907; Trap Rd order shows no survey
July 1902; Trap Rd order shows no survey

Re monumentation certificate prepared 5/31/01
 Filed at Cass Co. Recorder #441842

By J. Walker
 Date _____