


Index No. V 21

CASS COUNTY LAND CORNER RECORD

T. 135 R. 32 M. 5TH Coordinates: X _____ Y _____
NE 35 Corner common to sections 25, 26, 35, 36



EXISTING SURVEYS

Original Government Survey

Year surveyed 1866

Original monument Post

Species	Bearing	Trees	Distance
<u>N. PINE</u>	<u>N. PINE</u>	<u>W. BIRCH</u>	<u>N. PINE</u>
<u>10"</u>	<u>16"</u>	<u>B"</u>	<u>20"</u>
<u>57 1/2 E</u>	<u>S30W</u>	<u>N24W</u>	<u>N16E</u>
<u>64 LKS.</u>	<u>21 LKS.</u>	<u>31 LKS.</u>	<u>7 LKS.</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

○ = Corner

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1985 9/16 By Surveyors office

Dug in intersection w/ backhoe, dug 10' N-S x 10' E-W

X 3' deep. Found 2" dia rotted stake down 1.25'

8/14/86 - set cast iron monument down 8"

Certificate - Curro - 1987 - Doc # 297508

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Bearing Trees, Reference Objects

<u>P.P.</u>	<u>Tele. Pedestal</u>	<u>Jack Pine</u>
		<u>3"</u>
<u>N46°W</u>	<u>S77°E</u>	<u>S51°E</u>
<u>44.86'</u>	<u>33.73'</u>	<u>58.41'</u>

Subsequent Corner Restoration

Year surveyed April 2004 By J. Leas # 42619

Location filed _____

Monument Cert. of Sur. Shows mon. found

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Certificate - Walt Curro - 1987

May 1902, Top rd order shows no survey

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____