


T. 136 R. 29 M. 5TH Coordinates: X _____ Y _____
NE 5 Corner common to sections 4, 5



○ = Corner

EXISTING SURVEYS

Original Government Survey	
Year surveyed	<u>1870</u>
Original monument	<u>C.C. Post</u>
Bearing Trees	
Species	<u>W. Pine</u> <u>N. Pine</u>
Diameter	<u>22"</u> <u>10"</u>
Bearing	<u>S 22 W</u> <u>S 31 E</u>
Distance	<u>14 LKS</u> <u>112 LKS</u>

Original Evidence Found	
Year of search	_____ By _____
Monument found	_____
Original Bearing Trees Found	
Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Subsequent Corner Restoration	
Year surveyed	<u>1910</u> By <u>JOHN CURO</u>
Location filed	<u>COUNTY SURVEY BOOK "A" P 318-328</u>
Monument	<u>END 4X4 POST AND STUMP OF OLD GOUT BIT!</u>
	<u>20" W. PINE S 32 W 9.2, AND FOOT OF SE BIT.</u>
	<u>1916 - JOHN CURO - COUNTY RESURVEY "E-21" I.M.</u>
	<u>1918 - E.B. HORST BOOK "E" P 57 END CURO'S CORNER</u>
Bearing Trees, Reference Objects	
Species	<u>1916 - Horst - also on microfilm - roll 115</u>
Diameter	<u>BK 76 P. 2 - 1.12 - set 9" diam. concrete</u>
Bearing	<u>post 3' long</u>
Distance	_____

Evidence of Subsequent Corner Restoration	
Year of search	<u>1916</u> By <u>F.F. Wilson</u>
	<u>Microfilm - roll 115 BK 76 P. 19-20</u>
	<u>END CURO'S CORNER.</u>
Bearing Trees, Reference Objects	
_____	_____
_____	_____
_____	_____
_____	_____

Subsequent Corner Restoration	
Year surveyed	_____ By _____
Location filed	_____
Monument	_____
	<u>Sept. 1904</u>
	<u>Top Road order shows no survey</u>

Evidence of Subsequent Corner Restoration Found	
Year of search	_____ By _____

