

Index No. \_\_\_\_\_

CASS COUNTY LAND CORNER RECORD

T. \_\_\_\_\_ R. \_\_\_\_\_ M. \_\_\_\_\_ Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

Corner common to sections \_\_\_\_\_



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Index No. E 13

CASS COUNTY LAND CORNER RECORD

T. 136 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 9 Corner common to sections 3, 4, 9, 10



EXISTING SURVEYS

**Original Government Survey**  
 Year surveyed 1870  
 Original monument POST

Species	Bearing	Trees	Distance
<u>B. Pine</u>	<u>B. Pine</u>	<u>B. Pine</u>	<u>B. Pine</u>
<u>8"</u>	<u>10"</u>	<u>7"</u>	<u>9"</u>
<u>N1E</u>	<u>N39W</u>	<u>S31W</u>	<u>S75E</u>
<u>35 LKS.</u>	<u>31 LKS.</u>	<u>40 LKS.</u>	<u>22 LKS.</u>

**Original Evidence Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

**Subsequent Corner Restoration**  
 Year surveyed 1916 By John Curo  
 Location filed COUNTY RESURVEY "E-21"  
 Monument IRON MONUMENT  
1916: E. of Post Box "C" P. 57 Twp J. M.  
- also on microfilm - call 115 8K76 P. 5

**Evidence of Subsequent Corner Restoration**  
 Year of search Nov 2003 By CCSO  
Found 2 1/4" ODIP w/ plumbers cap, bent,  
spike at bend, down 1.3"

**Bearing Trees, Reference Objects**

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

**Bearing Trees, Reference Objects**

Species	Diameter	Bearing	Distance
<u>Pin Oak</u>	<u>6"</u>	<u>N 39° E</u>	<u>102.93'</u>
<u>Tel. Rod. Post</u>	<u>WOOD SAP</u>	<u>S 38° W</u>	<u>99.91'</u>
<u>P-Pole</u>	_____	<u>N 48° W</u>	<u>48.99'</u>

dbl hd nail E. side dbl hd nail E. dbl hd nail E.

**Subsequent Corner Restoration**  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
OCT 1999 B. GRIVNA  
CERT of SURV SHOWS MON FOUND  
August 1903  
Twp Board Order shows no survey

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_