

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____


Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

T. 136 R. 29 M. 5TH Coordinates: X _____ Y _____
N¹/₄ 8 Corner common to sections 5, 8



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument POST

Bearing Trees

Species	<u>N. PINE</u>	<u>ASPEN</u>	_____
Diameter	<u>24"</u>	<u>4"</u>	_____
Bearing	<u>S47E</u>	<u>N67E</u>	_____
Distance	<u>136 LKS</u>	<u>110 LKS</u>	_____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1918 By J. H. FLYNN
Location filed COUNTY RESURVEY "E-22"
Monument # 2 1/2 x 40" IRON MONUMENT
1918 - County Book "C" P. 138. FND J. H. FLYNN
1916, JOHN POMASEL, BOOK "C" P. 231 SET 7 1/4" IRON PIPE
also on microfilm - roll 105 BK 62 P. 42

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Evidence of Subsequent Corner Restoration

Year of search 5-13-04 By B. Graving # 17253
CCRO # A000488021
1/2" iron pipe in S2nd Street

Bearing Trees, Reference Objects

Power Pole	Power Pole	Corner Fence Post
<u>N80°W</u>	<u>N80°E</u>	<u>South</u>
<u>238.44'</u>	<u>231.07'</u>	<u>38.27'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____
August 1903
Twp Road Order shows no survey
November 1910
Twp Road order shows no survey

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____