


T. 136 R. 29 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 9 Corner common to sections 9, 10



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870  
Original monument Post

Original Evidence Found

Year of search 1900 by Whitely  
Monument found post  
Crow Wing, Book W-13, page 66

Bearing Trees

Species Norway Pine Black Pine  
Diameter 20" 8"  
Bearing S 35° W S 59° E  
Distance 115 links 30 links

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1903 By L.E. Garrison  
Location filed: Crow Wing, 1903 Book, page 61  
Monument: Set post from stumps of original bearing trees.

Evidence of Subsequent Corner Restoration

Year of search 7/1915 By J. Ingram  
Location filed: Loon Lake Township Road Order #4  
Monument: Iron monument

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 2/1948 By H.J. Curo, LS 3417  
Location filed: Curo Book 284, pages 5, 10, 11 and 14  
Monument: I.M.  
Set Red Flag, at I.M. cor. bet sec 9-10-136-29 and witnesses.  
4" Cherry, S 26°16' W, 34.10'  
8" Tele. Pole, N 76°07' W, 125.20'  
8" Light Pole, N 32°20' E, 48.60'  
6" Red Oak, S 56°37' E, 57.05'

Evidence of Subsequent Corner Restoration Found

Year of search 1996 By Landecker  
Location filed: Crow Wing, Certificate of Survey 10/136/29  
Monument:

3/1951, D. Cole, Cass County Engineer  
Project S.P. 11-509-01  
Indicates iron pipe for 1/4 corner at PI station 282+02.2 and witnesses as follows  
Power Pole, SE, 48.60'  
6" Oak, SW, 57.10'  
Tele Pole, NE, 125.20'

11/1997, B. Grivna, LS 17253  
Certificate of Survey for Nelson, #5495  
Indicates found iron monument.

10/1999, B. Grivna, LS 17253  
Certificate of Survey for Mortenson, #1529  
Indicates found iron monument.

7/2002, D.S. Landecker, LS 17008  
Certificate of Survey for Murrer, #1598  
Indicates found iron monument.

1971, D.M. Anderson, LS 3091  
Crow Wing, Book 216, page 53  
Found 3" capped monument, down 10".

11/2003, MN/DOT  
Crow Wing, Certificate of Location  
Found 3/4" pin, down 0.2', and witnesses.  
Power Pole, N 32° E, 50.70' duplex nail/SRP, up 0.5', NW side  
Tele Ped Post, N 86° W, 58.88' duplex nail/SRP, up 1.0', S side  
12" Red Oak, S 58° E, 57.23' duplex nail/SRP, up 1.0', NE side

1995, Landecker  
Crow Wing, Certificate of Survey  
10/136/29

T. 136 R. 29 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

E 1/4 9 Corner common to sections \_\_\_\_\_

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed 5/2004 By P.A. Trottier, LS 41002

Year of search \_\_\_\_\_ By \_\_\_\_\_

Location filed: Certificate of Survey for Nachbar, #2381

Location filed:

Monument: Indicates found monument.

Monument:

4/2008, Crow Wing Co. Surveyors Office  
Book CWC 128, page 32, Certificate #1359  
Found 3/4" solid pin.


1/2015, MN/DOT  
Certificate of Location  
Found 3/4" pin, down 0.3' in bituminous and 2003 witnesses.

8/2018, CCHD/SO  
#2018.019  
Found 7/8" ODIP, down 0.3', on centerline extension of Sibley Lake Rd., 8'+/-, N. of Lakeside Ave. and witnesses.  
Tele. Ped. Post, N 80° W, 58.92' brass SRP, up 0.9', S. side  
Drop Pole, N 22° E, 50.71' brass SRP, up 0.9', W. side  
8" Burr Oak, S 70° E, 66.12' duplex nail, up 1.0', S. side

Index No. G 13

CASS COUNTY LAND CORNER RECORD

T. 136 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E114 9 Corner common to sections 9, 10



EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1870  
 Original monument POST

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Bearing Trees  
 Species N. PINE B. PINE  
 Diameter 20" 8"  
 Bearing S35W S59E  
 Distance 115 LKS. 30 LKS.

Original Bearing Trees Found  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed 1950 By Co Hwy Dept  
 Location filed CRD # 17  
 Monument Found I.P.

Evidence of Subsequent Corner Restoration  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects  
 Species P.P. spike in oak  
 Diameter spike tele. pole 6"  
 Bearing SE NE SW  
 Distance 48.6' 125.2' 57.1'  
 or NE or SE or NW

Bearing Trees, Reference Objects  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument 7/2002 D. Landecker  
Cert of Svy shows mon found  
May 2004 P. Trotter # 41002  
Cert. of Svy shows mon. found  
July 1915 J. Ingram  
Trap Road order shows survey

Evidence of Subsequent Corner Restoration Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
OCT 1999 B. GRUNA  
CERT OF SVY SHOWS MON FOUND

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_