


Index No. G 5

CASS COUNTY LAND CORNER RECORD

T. 136 R. 29 M. 5TH Coordinates: X _____ Y _____
E 1/4 Corner common to sections 7, 8



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>SPRUCE</u>	<u>ASPEN</u>	_____
Diameter	<u>8"</u>	<u>12"</u>	_____
Bearing	<u>N58E</u>	<u>N29W</u>	_____
Distance	<u>25 LKS.</u>	<u>100 LKS.</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1913 By HARRY TODD
 Location filed COUNTY SURVEY RECORD BOOK "B" P 309
 Monument SET HVA PROPORTIONALLY
1917, E.B. HORST BOOK "B" P. 503 - 506 I.M. IMPROVE
1918, J.H. FLYNN, COUNTY RESURVEY "E-22" 2148' I.M.
1918, J.H. FLYNN COUNTY BOOK "C" P. 138 F.V.D. I.M.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

 _____ also on microfilm - roll 105 BK 62 P. 64

Bearing Trees, Reference Objects

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed 5-13-04 By B. Griuna # 17253
 Location filed CCRO # A000488023
 Monument 1/2" iron pipe capped RLS # 17253
in center of Twp. Rd.

Corner Fence Post	<u>Elm</u>	Corner Fence Post
<u>N 30° W</u>	<u>19"</u>	<u>East</u>
<u>46.40'</u>	<u>S 30° E</u>	<u>32.95'</u>
	<u>44.05'</u>	

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

December 1913 Harry S. Todd
Twp Road Order shows survey

Remonumentation certificate prepared _____
 Filed at _____

By _____
 Date _____