


Index No. P 13

CASS COUNTY LAND CORNER RECORD

T. 136 R. 29 M. 5TH Coordinates: X _____ Y _____
E114 21 Corner common to sections 21, 22



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870

Original monument POST

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	<u>N. PINE</u>	<u>N. PINE</u>	_____	_____
Diameter	<u>12"</u>	<u>10"</u>	_____	_____
Bearing	<u>S 41 W</u>	<u>S 54 E</u>	_____	_____
Distance	<u>55 LKS</u>	<u>48 LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1998 By CCSO

Inpl. DNR stamped washer & nail in an I.P.

28' E of twp rd.

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

<u>Maple</u>	<u>N. Pine</u>	<u>R. Oak</u>	<u>R. Oak Stump</u>
<u>10"</u>	<u>20"</u>	<u>9"</u>	<u>8"</u>
<u>N 52° W</u>	<u>S 75° W</u>	<u>N 89° E</u>	<u>S 50° E</u>
<u>77.08'</u>	<u>102.61'</u>	<u>45.45'</u>	<u>42.4'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - GARY STEVENSON - DNR - 1978

Doc. # 258659

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____