| 5 1/16 21 Corner common to sections ZI   | AND CC                               | 2   |  |
|--|--------------------------------------|---|--|
|  | STING SURVEYS                        | 1211                                      |  |
| Original Government Survey   | Original Evidence Found              |   |  |
| Year surveyed  | Year of searchBy                     |   |  |
| Original monument  | Monument found                       |   |  |
| Species Bearing Trees  | Original Bearing Trees Found Species | O = Corner                                |  |
| Diameter   |                                      |   |  |
| Bearing  |                                      |   |  |
| Distance   | Distance                             |   |  |
| Subsequent Corner Restoration  |                                      | Evidence of Subsequent Corner Restoration |  |
| Year surveyed 1998 By CCSO  Location filed  Monument Set 12" IDIP 16' E of & two rd.  33' S of & Driveway Ent. | Year of search By                    |   |  |
| Bearing Trees, Reference Objects Species R. Pine R. Oak Diameter 10" 12"                                       |                                      | ·   |  |
| Bearing 575°W N 25°E  Distance 84.08′ 63.25′  Subsequent Corner Restoration                                    |                                      |   |  |
| Subsequent Corner Restoration  ar surveyed By  | Evidence of Subsequent Corner        | Restaration Found                         |  |
| Subsequent Corner Restoration  ar surveyed By cation_filed   | Evidence of Subsequent Corner        | Restaration Found                         |  |
| Subsequent Corner Restoration  ar surveyed By cation_filed   | Evidence of Subsequent Corner        | Restaration Found                         |  |
| Subsequent Corner Restoration  ar surveyed By cation_filed   | Evidence of Subsequent Corner        | Restaration Found                         |  |
| Subsequent Corner Restoration  ar surveyed By cation_filed   | Evidence of Subsequent Corner        | Restaration Found                         |  |
| Subsequent Corner Restoration  ar surveyed By cation_filed   | Evidence of Subsequent Corner        | Restaration Found                         |  |
| Subsequent Corner Restoration  ar surveyed By cation_filed   | Evidence of Subsequent Corner        | Restaration Found                         |  |
| Subsequent Corner Restoration  ar surveyed By  | Evidence of Subsequent Corner        | Restaration Found                         |  |
| Subsequent Corner Restoration  ar surveyed By cation_filed   | Evidence of Subsequent Corner        | Restaration Found                         |  |
| Distance 84.08' 63.25'   | Evidence of Subsequent Corner        | Restaration Found                         |  |
| Subsequent Corner Restoration  ar surveyed By cation_filed   | Evidence of Subsequent Corner        | Restaration Found                         |  |
| Subsequent Corner Restoration  ar surveyed By  | Evidence of Subsequent Corner        | Restaration Found                         |  |