


T. 136 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 29 Corner common to sections 20, 21, 28, 29



EXISTING SURVEYS

Original Government Survey				
Year surveyed <u>1870</u>				
Original monument <u>POST</u>				
Species	Bearing	Trees		
<u>B. PINE</u>	<u>B. PINE</u>	<u>N. PINE</u>	<u>N. PINE</u>	
Diameter <u>8"</u>	<u>6"</u>	<u>14"</u>	<u>14"</u>	
Bearing <u>N76E</u>	<u>N60W</u>	<u>S77W</u>	<u>S7E</u>	
Distance <u>50 LKS</u>	<u>81 LKS</u>	<u>48 LKS</u>	<u>65 LKS</u>	

Original Evidence Found	
Year of search _____	By _____
Monument found _____	
Original Bearing Trees Found	
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Subsequent Corner Restoration	
Year surveyed <u>1909</u>	By <u>John Curo</u>
Location filed <u>COUNTY SURVEY RECORD BOOK "A" P 571-575</u>	
Monument <u>FOUND OLD GALT B.T.S: 8" B. PINE N76E 50 LKS, 14" N. PINE S7E 65 LKS, STUMP 14" N. PINE S77W 48 LKS, 1913 - HARRY TODD - BOOK "D" P 305-309, FOUND OLD GALT B.T.S: 14" N. PINE S7E 65 LKS, STUMP 8" B. PINE N76E 50 LKS, STUMP 14" N. PINE S77W 48 LKS, ROOTS 6" B. PINE N60W 81 LKS SET 2x4" GALV. I.P.</u>	
Bearing Trees, Reference Objects	
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Evidence of Subsequent Corner Restoration			
Year of search <u>1957</u>	By <u>H. Curo</u>		
<u>COUNTY BOOK "D" P. 431. FOUND SINGG OF OLD B.T. 12" J. PINE N53-12W 73.30' AND ALSO 2 1/2" x 48" J. M. W/ CAP.</u>			
Bearing Trees, Reference Objects			
<u>BIRCH</u>	<u>J. PINE</u>	<u>J. PINE</u>	<u>J. PINE</u>
<u>8"</u>	<u>10"</u>	<u>5"</u>	<u>6"</u>
<u>S28-05W</u>	<u>N72-07E</u>	<u>N44-07W</u>	<u>S36-04E</u>
<u>27.40'</u>	<u>80.95'</u>	<u>66.45'</u>	<u>35.35'</u>

R-9

Subsequent Corner Restoration	
Year surveyed <u>1958</u>	By <u>Mmn PNR-ENGINEERING</u>
Location filed <u>OFFICE m ST. PAUL</u>	
Monument <u>did not find l.p. - but find R.R. spike at intersection of roads. reset cap with an iron pipe set R.R. spike in top of l.p.</u>	
TREES:	
<u>Small nail sw side Tpk. Pole NW 58.84'</u>	
<u>Small nail nw side 7" J. Pine SW 37.36'</u>	
<u>Small nail sw side 7" J. Pine SE 40.10'</u>	
<u>also find E 1/4 B.T.W 20, 29 2" l.p.</u>	
<u>January 1926, J. Curo</u>	
<u>Two road order indicates corner</u>	
<u>May 2005 P. Trotter # 41002</u>	
<u>Cert of Survey shows monument found</u>	
<u>May 1925 John W. Curo</u>	
<u>Two Road Order indicates corner</u>	

Evidence of Subsequent Corner Restoration Found	
Year of search <u>1998</u>	By <u>CCSO</u>
<u>Inpl. 3" x 3" sq. aluminum cap flush with rd. Located 4.4' S of E Co. Rd. 168. No information on cap.</u>	
<u>dbl. hd. nail 6" R. Oak</u>	<u>91.88' N 64° W</u>
<u>" " " 7" J. Pine</u>	<u>89.02' N 53° E</u>
<u>" " " 9" J. Pine</u>	<u>57.67' S 10° E</u>
<u>6" J. Pine</u>	<u>61.00' S 35° W</u>
<u>1/2003 Landecker &amp; Assoc found alum. cap and 3 CCSO witnesses, added the following:</u>	
<u>10" Aspen</u>	<u>S 45° W, 43.10'</u>
<u>Certificate filed</u>	
<u>January 1926 John Curo</u>	
<u>Two Road order shows survey</u>	
<u>August 1905 W.H. Huffman</u>	
<u>Two Road order shows survey</u>	

Remonumentation certificate prepared   
Filed at CCRO document # 462471

By RLS 17008  
Date 2/14/03