


Index No. T 5

CASS COUNTY LAND CORNER RECORD

T. 136 R. 29 M. 5TH Coordinates: X _____ Y _____
E 1/4 30 Corner common to sections 29, 30



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	Bearing	Distance
<u>N. PINE</u>	<u>N. PINE</u>	
<u>18"</u>	<u>20"</u>	
<u>S44E</u>	<u>N61W</u>	
<u>16 LKS</u>	<u>16 LKS</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1909 By JOHN CURD
Location filed COUNTY SURVEY RECORD BOOK 'A' P. 571-575
Monument SET STAKE PROPORTIONALLY

Evidence of Subsequent Corner Restoration

Year of search 6/2002 By Landecker & Assoc
No evidence of corner. Set 1/2" pipe
RLS 41002, at single proportion.
3.5' E. of & 17th Ave.
Certificate filed

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>PINE STUMP</u>	<u>PINE STUMP</u>	
_____	_____	_____
<u>NE</u>	<u>NW</u>	
<u>22.65'</u>	<u>23.30'</u>	

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>P. Pole</u>	<u>N. Pine</u>	<u>N. Pine</u>	
_____	<u>15"</u>	<u>15"</u>	
<u>N24°E</u>	<u>East</u>	<u>S38°W</u>	
<u>28.76'</u>	<u>66.45'</u>	<u>91.05'</u>	

T-5

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____
Feb. 2005 J Leas #42619
Cert of Survey shows monument found

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____
Filed at CCRO document #462472

By RLS 17008
Date 2/14/03