


Index No. V 9

CASS COUNTY LAND CORNER RECORD

T. 136 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 32 Corner common to sections 28, 29, 32, 33



○ = Corner

EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1870  
Original monument post

Species	Bearing	Trees	Distance
<u>Sp. Pine</u>	<u>04K</u>	<u>B. Pine</u>	<u>86 LKS</u>
<u>10"</u>	<u>16"</u>	<u>10"</u>	<u>90 LKS</u>
<u>S13W</u>	<u>S27E</u>	<u>N65.W</u>	<u>N5E</u>
<u>31 LKS</u>	<u>42 LKS</u>	<u>86 LKS</u>	<u>90 LKS</u>

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

**Subsequent Corner Restoration**

Year surveyed 1/2003 By Landecker & Assoc  
Location filed Perquod Office  
Monument Found 1 1/2" iron pipe, w/ 1.5' 44' ± SW of trail. Certificate filed

**Evidence of Subsequent Corner Restoration**

Year of search May 1925 By J. Curo  
Twp Road order indicates corner

**Bearing Trees, Reference Objects**

Species	Bearing	Distance
<u>Poplar</u>	<u>N16°E</u>	<u>15.68'</u>
<u>Ji Pine</u>	<u>5.84°E</u>	<u>67.85'</u>
<u>Ji Pine</u>	<u>5.35°E</u>	<u>7.78'</u>
<u>Poplar</u>	<u>West</u>	<u>5.19'</u>

**Bearing Trees, Reference Objects**

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

V-9

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument Oct 1983 M. Landecker Plat of Svy. shows man found  
January 1926 John Curo Twp Road order shows survey  
May 1925 John W. Curo Twp Road order shows survey

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

Re monumentation certificate prepared \_\_\_\_\_  
Filed at CCRO document #462476

By RLS 17008  
Date 2/14/03