


Index No. A 11

CASS COUNTY LAND CORNER RECORD

T. 136 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

N 1/4 4 Corner common to sections 4



EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1977 By R.F. Schneider  
Location filed For Hwy Dept - Co Rott #28  
Monument Corner position from road stationing

Evidence of Subsequent Corner Restoration

Year of search 7/01 By CCSO  
Found alum cap telescope mon. Flush on  
E cord #28.

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

<u>R. Oak</u>	<u>R/A tie post</u>	<u>R. Oak</u>
<u>5"</u>		<u>6"</u>
<u>N 30° E</u>	<u>S 70° E</u>	<u>N 18° W</u>
<u>136.93'</u>	<u>160.35'</u>	<u>135.70'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument Corner - GPS 9/12/02 CCSO  
Alum cap

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_

Filed at \_\_\_\_\_ Date \_\_\_\_\_