Index No. A 15

CASS COUNTY LAND CORNER RECORD

T. 136 R. 30 M. 5TH Coordinates: X _____ Y _____

N1/4 3 Corner common to sections 3



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1977 By R.F. Schneider

Location filed for Hwy Dept Co Rd #28

Monument Corner position from road stationing

Evidence of Subsequent Corner Restoration

Year of search 7/01 By CCSO

Found alum cap telespar mon. flush, 1.0' S. of ℄ co rd #28 125' ± E of approach

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Bearing Trees, Reference Objects

W. Oak	W. Oak
8"	10"
S 38° E	S 38° W
121.11'	136.68'

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed

Monument - Corner GPS 9/12/02 - CCSO

Alum cap

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____