

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. N 17

CASS COUNTY LAND CORNER RECORD

T. 136 R. 30 M. 5TH Coordinates: X _____ Y _____
NE 22 Corner common to sections 14, 15, 22, 23



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing Trees			
Species	<u>W. OAK</u>	<u>ASPEN</u>	<u>ASPEN</u>	<u>W. BIRCH</u>
Diameter	<u>10"</u>	<u>12"</u>	<u>4"</u>	<u>8"</u>
Bearing	<u>N42W</u>	<u>S40W</u>	<u>N65E</u>	<u>S1E</u>
Distance	<u>73 LKS</u>	<u>70 LKS</u>	<u>30 LKS</u>	<u>35 LKS</u>

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed --- By SURVEY OF S. R. HWY 80
Location filed COUNTY BOOK B " 6474-475
Monument 2" I.P.

Evidence of Subsequent Corner Restoration

Year of search 1955 By Co. Hwy Dept
Co RD # 1
Found 3" steel disc

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

<u>Birch</u>	<u>Birch</u>	<u>Tele. Pole</u>
<u>4"</u>	<u>8"</u>	
<u>SW</u>	<u>W.</u>	<u>SE</u>
<u>58.4'</u>	<u>72.4'</u>	<u>37.2'</u>

Subsequent Corner Restoration

Year surveyed 1914 By _____
Location filed _____
Monument Co DITCH SURVEY BK 22 BOX 3 OF
Co DITCH SURVEY BOOKS, PG 51

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

1985 FREEMAN - NO EVIDENCE
Oct 1909 W.H. Luffman
Twp Road order shows survey
Jan 1916 Twp Rd Order shows no survey
Dec. 1917 Twp Rd order shows no survey

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____