


Index No. P9

CASS COUNTY LAND CORNER RECORD

T. 136 R. 30 M. 5TH Coordinates: X _____ Y _____
E 14 R 20 Corner common to sections 20, 21



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument Pest

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>BIRCH</u>	<u>BIRCH</u>	_____	_____
Diameter	<u>10"</u>	<u>11"</u>	_____	_____
Bearing	<u>N24W</u>	<u>N51/2E</u>	_____	_____
Distance	<u>10 LKS</u>	<u>13 LKS.</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Bearing Trees, Reference Objects

Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____
Oct. 1904 Twp Road order shows no survey

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

