


Index No. V 25

CASS COUNTY LAND CORNER RECORD

T. 136 R. 30 M. 5TH Coordinates: X _____ Y _____
NE 36 Corner common to sections 25, 36 AND 30, 31-136-29



EXISTING SURVEYS

Original Government Survey

Year surveyed 1858
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing Trees			
	<u>PINE</u>	<u>PINE</u>	<u>PINE</u>	<u>Aspen</u>
Diameter	<u>12"</u>	<u>13"</u>	<u>10"</u>	<u>10"</u>
Bearing	<u>S19E</u>	<u>S20W</u>	<u>N76 1/2 W</u>	<u>N29 1/2 W</u>
Distance	<u>36 LKS</u>	<u>22 LKS</u>	<u>13 LKS</u>	<u>25 LKS</u>

Original Bearing Trees Found

Species			
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1916 By E. D. Horst
Location filed County Survey Record Book 'B' P 334-338
Monument Two Old Gout O.T.S. Stump 13" Bl. Pine S19E
36 LKS, SET 2x48 IRON

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>J. PINE</u>	<u>W. PINE STUMP</u>
Diameter	<u>10"</u>	<u>18"</u>
Bearing	<u>S33E</u>	<u>S33W</u>
Distance	<u>98.00'</u>	<u>52.90'</u>

Bearing Trees, Reference Objects

Species		
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
August 1909
Trap Road order shows no survey

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____